Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/Client 50005DE8426/1

Work Order Type: Weatherization Audit Name: Audit DE8426

CLIENT INFORMATION

Client Name: Address:

Client ID: Client 50005DE8426 , TN

Alt. Client ID:

AGENCY INFORMATION

Agency: 50005DE **Agency Phone:** (901) 476-5226

Address: P. O. BOX 634, 915 HWY 51 SOUTH **Fax:** (901) 476-5258

Agency Contact: Treadwell, Dwight Work Phone: (901) 274-8336

Cell Phone: (865) 335-4834

Email Address:

| Company Name & License Number: | |
|--------------------------------|--|
| Contractor's Signature: | |

COMMENT

Measures

| - | Measure 1 | Replace broken pane in W4 | ı | | Componen | ts | | | nspected |
|------------|---|---|------------------------------|--------------|---------------------|------------|------------------|------------------|-----------|
| C | omment | | | | | | | | |
| | | | | | Estimated | 1 | | Actual | |
| # | Material / Labo | or Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 10 | Unspecified | Misc Material | Each | 1 | | | | | |
| C | ther Detail | | | | | | | | |
| Ĭ | ther Betain | | | | | | | | |
| | | | | | | | | | |
| _ | | | | Mossur | e Sub Total: | | اـــــــا ا ا | Sub Total: | |
| Г | Field Notes: | | | INCASUI | e Sub Total. | | , | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| L | | | | | | | | | |
| | Measure 2 | Replace kitchen door | | | Componen | ts | | | nspected |
| | | • | core door - | Recor | • | | door | 1 | Inspected |
| | omment Kitc | Replace kitchen door hen door very filmsy hollow o | core door - | Recor | • | | door | ı | Inspected |
| | omment Kitc | hen door very filmsy hollow o | core door - | Recor | • | acing this | door | Actual | Inspected |
| C | omment Kitc | hen door very filmsy hollow o standard size door | core door - <i>Unit</i> s | Recor | nmend repla | acing this | door | | Inspected |
| <i>C</i> # | omment Kitc with | hen door very filmsy hollow o standard size door | | | mmend repla | acing this | | Actual | |
| # 10 | omment Kitc with Material / Labo | hen door very filmsy hollow of standard size door Or Description / Comment | Units | Qty | mmend repla | acing this | | Actual | |
| # 10 | omment Kitc with Material / Labo Unspecified | hen door very filmsy hollow of standard size door Or Description / Comment | Units | Qty | mmend repla | acing this | | Actual | |
| # 10 | omment Kitc with Material / Labo Unspecified | hen door very filmsy hollow of standard size door Or Description / Comment | Units | Qty | mmend repla | acing this | | Actual | |
| # 10 | omment Kitc with Material / Labo Unspecified | hen door very filmsy hollow of standard size door Or Description / Comment | Units Each | Qty 1 | mmend repla | acing this | Qty | Actual | |
| # 10 | omment Kitc with Material / Labo Unspecified other Detail | hen door very filmsy hollow of standard size door Or Description / Comment | Units Each | Qty 1 | Estimated Unit Cost | acing this | Qty | Actual Unit Cost | |
| # 10 | omment Kitc with Material / Labo Unspecified | hen door very filmsy hollow of standard size door Or Description / Comment | Units Each | Qty 1 | Estimated Unit Cost | acing this | Qty | Actual Unit Cost | |
| # 10 | omment Kitc with Material / Labo Unspecified other Detail | hen door very filmsy hollow of standard size door Or Description / Comment | Units Each | Qty 1 | Estimated Unit Cost | acing this | Qty | Actual Unit Cost | |
| # 10 | omment Kitc with Material / Labo Unspecified other Detail | hen door very filmsy hollow of standard size door Or Description / Comment | Units Each | Qty 1 | Estimated Unit Cost | acing this | Qty | Actual Unit Cost | |

| ı | Measure 3 Re | eplace window sill in W12 | | | Componen | its | | ı | Inspected |
|----|---|--|----------------------|-----------|--------------|----------|------|------------|-----------|
| C | omment | | | | | | | | |
| | | | | | Estimated | <u> </u> | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 10 | Unspecified | Misc Material | Each | 1 | | | | | |
| C | Other Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | |] ; | Sub Total: | |
| | Field Notes: | | | | | | | | |
| C | 1.Sea 2. Cal 3.Add 4. We 5. Blo | NFILTRATION MEASURES I all plumbing penetrations uk W2, W8, W9 thresold to Front door atherstrip Front and two atti ck and Seal W2 and large v ch crack in living room and | ic access vall AC | | | | | | |
| | 0.1 0. | on order in living room and | anning roc | JIII 00II | Estimated | ı | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 10 | Miscellaneous | Infiltration Reduction | Each | 1 | | | | | |
| | Supplies | | | | | | | | |
| C | Other Detail | | | | | | | | |
| | | | | | | |] [] | | |
| L | | | | | | |] | | |
| | | | | Measur | e Sub Total: | | , | Sub Total: | |
| | Field Notes: | | | | | | | | |

| | Measure 5 DW | /H Tank Insulation | | | Componen | | | Inspected | |
|--------------------|--|--|-------------------|----------------|-----------------------|----------|-----|------------------|-----------------|
| C | omment Water | heater located in attic - ne | ed to insu | late | | | | | |
| | | | | | Estimated | <u> </u> | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Hot Water Equipment | DHW Tank Insulation | Each | 1 | | | | | |
| 2 | Labor | DHW Tank Insulation | Each | 1 | | | | | |
| C | Other Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | |] ; | Sub Total: | |
| | Field Notes: | | | | | | | | |
| | | | | | | | | | |
| | Measure 6 DW | /H Pipe Insulation | | | Componen | nts | | | Inspected |
| | | /H Pipe Insulation | | | Componen Estimated | | | Actual | Inspected |
| C | | /H Pipe Insulation Description / Comment | Units | Qty | - | | Qty | | Inspected Total |
| <i>C</i> | omment | - | <i>Units</i> Each | | Estimated | 1 | Qty | Actual | |
| C # | omment Material / Labor | Description / Comment | | Qty | Estimated | 1 | Qty | Actual | |
| C # 1 | Material / Labor Insulation | Description / Comment DHW Pipe Insulation | Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| c # 1 | Material / Labor Insulation Labor | Description / Comment DHW Pipe Insulation | Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| C # 1 | Material / Labor Insulation Labor | Description / Comment DHW Pipe Insulation | Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| C # 1 | Material / Labor Insulation Labor | Description / Comment DHW Pipe Insulation | Each | Qty 1 1 | Estimated | 1 | | Actual | |
| C # 1 | Material / Labor Insulation Labor | Description / Comment DHW Pipe Insulation | Each | Qty 1 1 | Estimated Unit Cost | 1 | | Actual Unit Cost | |
| C # 1 | Material / Labor Insulation Labor Other Detail | Description / Comment DHW Pipe Insulation | Each | Qty 1 1 | Estimated Unit Cost | 1 | | Actual Unit Cost | |

| Measure 7 Attic | Ins. R-38 | | | Componen | <i>ts</i> 364 S | q.ft Add | dition | nspecte |
|---------------------------|---|-------|--------|---------------------|-----------------|----------|-------------|---------|
| | llation in the main part of llings have large cracks and | | | | | | 9 | |
| | | | | Estimated | | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| Insulation | Attic Insulation - Blown Cellulose - R-38 | SqFt | 364 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | |] ; | Sub Total: | |
| Field Notes: | | | | | | | | |
| Measure 8 Repl Comment | ace A/C | | | Componen Estimated | ts AC | | l Actual | nspecte |
| Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| Cooling Equipment | Window A/C - | Each | 1 | | | | | |
| Labor | Window A/C - | Each | 1 | | | | | |
| Other Detail | | | | | | 1 | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | - | | |
| | | | Measur | e Sub Total: | | , | Sub Total: | |
| Field Notes: | | | Measur | e Sub Total: | | | Sub Total: | |
| Field Notes: | | | Measur | e Sub Total: | | | Sub Total: | |

| ı | Measure 9 Ref | rigerator Rplcmnt | | | Componen | ts | | | Inspected |
|----|-----------------------|---|-----------|----------|------------------|-----------|-------|------------|-----------|
| C | omment | | | | | | | | |
| | | | | | Estimated | <u> </u> | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 10 | Refrigerators | - | Each | 1 | | | | | |
| C | Other Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | |
| | Field Notes: | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | <i>Measure</i> 10 Rep | olace Htg. System | | | Componen | ts 50,000 |) BTU | vented | Inspected |
| С | unvente Recom | wner has one older mode ed gas wall heater. mending replacing the un BTU wall heater and rem | vented wa | ıll heat | er with a Ve | nted Sing | ıle | | |
| | , | | J | | Estimated | | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Heating Equipment | Space Heater - 20 kBtu/h NG Existing, 48 - | Each | 1 | | | | | |
| | | 67 kBtu/h NG Post | | | | | | | |
| 2 | Labor | Space Heater - 20 kBtu/h NG Existing, 48 - | Each | 1 | | | | | |
| | | 67 kBtu/h NG Post | | | | | | | |
| C | Other Detail | | | | | |] | | |
| L | | | | | | |] [| | |
| | | | | | | |] [| | |
| | | | | Measur | e Sub Total: | | | Sub Total: | |
| | Field Notes: | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| | Measure 11 Install Carbon Detector | | | | Componen | ts | Inspected | | | |
|---|------------------------------------|-----------------------|--------|----------|--------------|-------|-----------|------------|-------|--|
| C | Comment | | | | | | | | | |
| | | | | | Estimated | 1 | | Actual | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| 1 | Health and Safety Items | material | Each | 1 | | | | | | |
| 2 | Labor | Labor | Each | 1 | | | | | | |
| (| Other Detail | | | | | | , | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | Measur | e Sub Total: | |] ; | Sub Total: | | |
| | Field Notes: | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | Work O | rder Gra | nnd Total: | | Gran | d Total: | | |